ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

# BBMP ENGINEERING DEPARTMENT

## Road History Data Sheet

### General

| Zone | Ward No. | Ward Name |
|---|---|---|
| YELAHANKA | 11 | Kuvempu Nagar |
| **Street ID** | **Street Name** | **Significant Landmark** |
| W0451 | NA | House |
| **Segment No.** | **Total Length (m)** | |
| 11/S-W0451/S011038 | 35.34 | |

**Segment Details**

| Seg No. | Length (m) | Start Coordinates | | End Coordinates | | From | To |
|---|---|---|---|---|---|---|---|
| 1 | 35.34 | 77.552645 | 13.081089 | 77.552592 | 13.080774 | Srinidhi Layout | Dead End |

### Work Details

**History of Road / Lane / Circles**

| Name of the Work | Sanctioned Estimated Amount (Rs.) | Sanctioned Year |
|---|---|---|
| Improvements to Roads and Drains at M.S Palya area in Ward No 11 (Kuvempunagara) in Vidyaranyapura Sub Division | 2000000 | 2017-18 |
| **Year** | **Type of Work** | **Other Work Type** |
| 2017 - 2018 | Drain Maintenance | |
| **Tender** | **Work Details** | **Job No. / Work Code** |
| Tender | Construction of RCC Drain | 011-18-000069 |
| **Work Order No.** | **Work Order Date** | **Period of Extention** |
| EE/BTP/BBMP/ E-PMT/29 (30480)/WO/101/2018-19 | 31/08/2018 | |
| **Defect Liability Period From** | **Defect Liability Period To** | **Multiple road involved with the same Job No/ Work Code #** |
| 04/10/2018 | 03/10/2019 | No |

### Contractor Details

| Name of Contractor | Contractor Reg No (BBMP/PWD) | Expenditure Booked \ Released (Rs) |
|---|---|---|
| N.M Shivakumar | | 0.00 |
| **Phone No.** | **E-Mail ID** | |
| 9448956136 | | |

Assistant Executive Engineer
Vidyaranyapura Sub Division
BBMP, Bangalore - 97



Scanned by CamScanner

## Field Inspection Details

| Number of Trees | Any Other Information | Name |
|---|---|---|
| 0 | | rajashekar murthy d n |

| Date of Inspection | Remarks |
|---|---|
| 10/10/2018 | |

| Category | Image | Photo Remark |
|---|---|---|
| Segment End | | This photo seems out of range. |
| Segment Start | | This photo seems out of range. |

## Remarks

| Designation | Approver Name | Date | Target Date | Remark |
|---|---|---|---|---|
| CE | R.L.Parameshwaraiah | 11/10/2018 | 09/11/2018 | As proposed |
| SE | Vasu K M | 11/10/2018 | 09/11/2018 | Completed |
| EE | Mohan Das H T | 10/10/2018 | 09/11/2018 | Verified |
| AEE | Shivakumar M Goudar | 10/10/2018 | 09/11/2018 | Verified |
| AE | Rajashekar Murthy D N | 10/10/2018 | 09/11/2018 | Mobile Verification Done |
| AE | Rajashekar Murthy D N | 10/10/2018 | 09/11/2018 | Forwarded |

Assistant Executive Engineer
Vidyaranyapura Sub Division
BBMP, Bangalore - 97



Scanned by CamScanner

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

# BBMP ENGINEERING DEPARTMENT

## Road History Data Sheet

### General

| Zone | Ward No. | Ward Name |
|---|---|---|
| YELAHANKA | 11 | Kuvempu Nagar |
| **Street ID** | **Street Name** | **Significant Landmark** |
| W0187 | NA | opp HKGN Bananna Mandi |
| **Segment No.** | **Total Length (m)** | |
| 11/S-W0187/S125008 | 100.84 | |

**Segment Details**

| Seg No. | Length (m) | Start Coordinates | | End Coordinates | | From | To |
|---|---|---|---|---|---|---|---|
| 1 | 100.84 | 77.552106 | 13.081684 | 77.551846 | 13.080809 | Srinidhi Layout | Hunasemar Road |

### Work Details

**History of Road / Lane / Circles**

| Name of the Work | Sanctioned Estimated Amount (Rs.) | Sanctioned Year |
|---|---|---|
| Improvements to Roads and Drains at M.S Palya area in Ward No 11 (Kuvempunagara) in Vidyaranyapura Sub Division | 2000000 | 2017-18 |
| **Year** | **Type of Work** | **Other Work Type** |
| 2017 - 2018 | Drain Maintenance | |
| **Tender** | **Work Details** | **Job No. / Work Code** |
| Tender | Construction of RCC Drain | 011-18-000069 |
| **Work Order No.** | **Work Order Date** | **Period of Extention** |
| EE/BTP/BBMP/ E-PMT/29 (30480)/WO/101/2018-19 | 31/08/2018 | |
| **Defect Liability Period From** | **Defect Liability Period To** | **Multiple road involved with the same Job No/ Work Code #** |
| 04/10/2018 | 03/10/2019 | No |

### Contractor Details

| Name of Contractor | Contractor Reg No (BBMP/PWD) | Expenditure Booked \ Released (Rs) |
|---|---|---|
| N.M Shivakumar | | 0.00 |
| **Phone No.** | **E-Mail ID** | |
| 9448956136 | | |

Assistant Executive Engineer
Vidyaranyapura Sub Division
BBMP, Bangalore - 97



Scanned by CamScanner

## Field Inspection Details

| Number of Trees | Any Other Information | Name |
|---|---|---|
| 0 | | rajashekar murthy d n |

| Date of Inspection | Remarks |
|---|---|
| 10/10/2018 | |

| Category | Image | Photo Remark |
|---|---|---|
| Segment End | | This photo seems out of range. |
| Segment Start | | This photo seems out of range. |

## Remarks

| Designation | Approver Name | Date | Target Date | Remark |
|---|---|---|---|---|
| CE | R.L.Parameshwaraiah | 11/10/2018 | 09/11/2018 | As proposed |
| SE | Vasu K M | 11/10/2018 | 09/11/2018 | Completed |
| EE | Mohan Das H T | 10/10/2018 | 09/11/2018 | Verified |
| AEE | Shivakumar M Goudar | 10/10/2018 | 09/11/2018 | Verified |
| AE | Rajashekar Murthy D N | 10/10/2018 | 09/11/2018 | Mobile Verification Done |
| AE | Rajashekar Murthy D N | 10/10/2018 | 09/11/2018 | Forwarded |

Assistant Executive Engineer
Vidyaranyapura Sub Division
BBMP, Bangalore - 97

**Zone:** YELAHANKA **Ward No:** 11 **Ward Name:** Kuvempu Nagar **Street ID:** W0187

Date: 15/10/2018 Time: 15:12:35 RI2018101515123...



Scanned by CamScanner

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

# BBMP ENGINEERING DEPARTMENT

## Road History Data Sheet

### General

| Zone | Ward No. | Ward Name |
|---|---|---|
| YELAHANKA | 11 | Kuvempu Nagar |
| **Street ID** | **Street Name** | **Significant Landmark** |
| W0176 | NA | 4th Cross Road |
| **Segment No.** | **Total Length (m)** | |
| 11/S-W0176/S125932 | 49.32 | |

**Segment Details**

| Seg No. | Length (m) | Start Coordinates | | End Coordinates | | From | To |
|---|---|---|---|---|---|---|---|
| 1 | 49.32 | 77.552457 | 13.081281 | 77.552008 | 13.081351 | Srinidhi Layout Main Road | Dead End |

### Work Details

**History of Road / Lane / Circles**

| Name of the Work | Sanctioned Estimated Amount (Rs.) | Sanctioned Year |
|---|---|---|
| Improvements to Roads and Drains at M.S Palya area in Ward No 11 (Kuvempunagara) in Vidyaranyapura Sub Division | 2000000 | 2017-18 |
| **Year** | **Type of Work** | **Other Work Type** |
| 2017 - 2018 | Drain Maintenance | |
| **Tender** | **Work Details** | **Job No. / Work Code** |
| Tender | Construction of RCC Drain | 011-18-000069 |
| **Work Order No.** | **Work Order Date** | **Period of Extention** |
| EE/BTP/BBMP/ E-PMT/29 (30480)/WO/101/2018-19 | 31/08/2018 | |
| **Defect Liability Period From** | **Defect Liability Period To** | **Multiple road involved with the same Job No/ Work Code #** |
| 04/10/2018 | 03/10/2019 | No |

### Contractor Details

| Name of Contractor | Contractor Reg No (BBMP/PWD) | Expenditure Booked \ Released (Rs) |
|---|---|---|
| N.M Shivakumar | | 0.00 |
| **Phone No.** | **E-Mail ID** | |
| 9448956136 | | |

Assistant Executive Engineer
Vidyaranyapura Sub Division



Scanned by CamScanner

## Field Inspection Details

| Number of Trees | Any Other Information | Name |
|---|---|---|
| 2 | | rajashekar murthy d n |

| Date of Inspection | Remarks |
|---|---|
| 13/10/2018 | |

| Category | Image | Photo Remark |
|---|---|---|
| Segment End | | This photo seems out of range |
| Segment Start | | This photo seems out of range |

## Remarks

| Designation | Approver Name | Date | Target Date | Remark |
|---|---|---|---|---|
| CE | A L Parameshwaraiah | 13/10/2018 | 26/11/2018 | Re proposed |
| SE | Vasu K M | 13/10/2018 | 26/11/2018 | Completed |
| EE | Mohan Das A L | 13/10/2018 | 26/11/2018 | Verified |
| AEE | Shivakumar M Gouder | 13/10/2018 | 26/11/2018 | Verified |
| AE | Rajashekar Murthy D N | 13/10/2018 | 26/11/2018 | Mobile Verification Done |
| AE | Rajashekar Murthy D N | 13/10/2018 | 26/11/2018 | Forwarded |

Assistant Executive Engineer
Vidyaranyapura Sub Division
BBMP, Bangalore - 97

Zone: YELAHANKA | Ward No: 41 | Ward Name: Kuvempu Nagar | Street ID: 442178

Date: 13/10/2018 | Time: 03:14:33 | 4041001010101433 | Page 2 of 2

Scanned by CamScanner